


NUMBER: TSNT01299538



Intertek Testing Services (Tianjin) Ltd. No. 7 Guiyuan Road, Huayuan Hi-Tech Park, Tianjin, 300384, P. R. China 天津华苑新技术产业园区桂苑路7号 邮编 300384 Tet +86 22 8371 2202 Fax: +86 22 8371 2205 Attention is drawn to the terms and conditions printed Page 1 of 3



NUMBER: TSNT01299538

Applicant :	Gabriel A/S China Office Rm 703, South Tower Soho Shangdu,No. 8 Dongdaqiao Road, Chaoyang District, Beijing,100020		Date :	Jun 19, 2020	
Attn :	Anne Dong				
Sample Description	n As Declared	:			
No. Of Sample	:	One			
Fibre Content	:	-			
Material	:	Woven Fabric			
Finishing	:	-			
End Uses	:	-			
Colour	:	61159 Beige			
Style No.	:	Sodley (FR YARN)			
Order No./PO N	lo. :	04252			
Buyer's Name	:	Gabriel			
Agent's Name	:	-			
Manufacturer's	Name :	-			
Date Received/Date Test Started : Jun 16, 2020					
Tests Conducted:					
As Requested By The Applicant, For Details Refer To Attached Page(S)					

Authorized By : For Intertek Testing Services (Tianjin) Ltd.

Persnicle

Patrick Gong General Manager

Page 2 of 3

Intertek Testing Services (Tianjin) Ltd. No. 7 Guiyuan Road, Huayuan Hi-Tech Park, Tianjin, 300384, P. R. China 天津华苑新技术产业园区桂苑路7号 邮编 300384 Tel: +86 22 8371 2202 Fax: +86 22 8371 2205 Attention is drawn to the terms and conditions printed



NUMBER: TSNT01299538

Tests Conducted:

1. Abrasion Resistance (DIN EN ISO 12947-2:2017, Martindale Abrasion And Pilling Tester, 12kPa Total Weight) :

Resistance: Face Side	
Specimen 1	50000 Rubs
Specimen 2	50000 Rubs
Specimen 3	50000 Rubs
Quoted Result	50000 Rubs

Change In Color After 6000 Rubs:

Type Of Fabric: Woven Fabric	Type Of Fabric:	Woven Fabric	
Type Of End-Point: Three Broken Thread	Type Of End-Point:	Three Broken Thread	

4

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.