



**For the Account of** Gabriel A/S  
Hjulgagervej 55  
9000 Aalborg Denmark

**Client's Identification** ARCH col. 70999

## CERTIFICATE OF TESTING

**TEST PERFORMED** Standard Test Method for Pilling Resistance and Other Related Surface Changes of Textile Fabrics :  
Brush Pilling Tester ASTM D3511/D3511M-16(2022)

### TEST RESULTS

	Rating
Left	5.0
Center	5.0
Right	5.0
Average Rating	5.0

### RATING SYSTEM

Class 5.0	No Pilling
Class 4.0	Slight Pilling
Class 3.0	Moderate Pilling
Class 2.0	Severe Pilling
Class 1.0	Very Severe Pilling

### NOTES

<b>Test Conditions</b>	70 ±4°F, 65 ±5% Relative Humidity
<b>Sampling Method</b>	As Received
<b>Viewing Apparatus</b>	Macbeth Lightbooth
<b>Viewing Option</b>	45 degree
<b>Rating Standard</b>	ADJD3512 Photographic Standards
<b>Running Times</b>	4 minutes brushing / 2 minutes pilling
<b>Material Tested</b>	As Received (no refurbishment), unless otherwise noted in Client Identification above

### ACCEPTANCE CRITERIA

#### ACT Performance Guideline Criteria

	Woven + Knitted
Upholstery <i>Indoor</i>	Class 3.0, min
Upholstery <i>Outdoor</i>	Class 3.0, min

**CERTIFICATION** I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Authorized Signature

Date Order Completed: 12/16/2025