



For the Account of: Gabriel A/S
Hjulgagervej 55
9000 Aalborg Denmark



Date of Issue: 6/6/2025
Report Number: 25-001546
Revision Number: 1
Date Order Received: 06/03/2025

Client's Identification: GO CHECK

CERTIFICATE OF TESTING

TEST PERFORMED: Standard Test Method for Pilling Resistance and Other Related Surface Changes of Textile Fabrics :
Brush Pilling Tester ASTM D3511/D3511M-16(2022)

TEST RESULTS

	Rating
Left	5.0
Center	5.0
Right	5.0
Average Rating	5.0

RATING SYSTEM

Class 5.0	No Pilling
Class 4.0	Slight Pilling
Class 3.0	Moderate Pilling
Class 2.0	Severe Pilling
Class 1.0	Very Severe Pilling

NOTES

Test Conditions:	70 ±4°F, 65 ±5% Relative Humidity
Sampling Method:	As Received
Viewing Apparatus:	Macbeth Lightbooth
Viewing Option:	45 degree
Rating Standard:	ADJD3512 Photographic Standards
Running Times:	4 minutes brushing / 2 minutes pilling
Material Tested:	As Received (no refurbishment), unless otherwise noted in Client Identification above

ACCEPTANCE CRITERIA

A.C.T. Standard:	Acceptance Criteria
Upholstery	Class 3 minimum

CERTIFICATION I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Jennifer Friend

Authorized Signature

Date Order Completed: 06/06/2025